

Differential Service Kits



Differential Service Kits

Application	Part Number	Spring Retainer Service Kit	Pinion Gear Service Kit	Pinion Shaft Service Kit
GM 7.5 & 7 5/8	542040, 41, 57, 58	541016	541011	541005
	542044, 45, 46, 47	541017	541011	541005
GM 8.5 & 8.6	542018, 22, 29, 97	541018	541012	541007
	542050, 52	541019	541012	541007
GM 8.2	542060, 61	541035	541036	541037
1963 -'79 Corvette	542062, 63	541035	541036	541037
GM 8 7/8 12 Bolt, Car & Truck	542031, 32, 33, 34	541022	541014	541009
GM 9.5 & 9.6	542087	541043	541044	541042
Ford 7.5	542023	541016	541011	541006
	542048	541017	541011	541006
Ford 8.8, 28 Tooth	542024, 79	541018	541012	541007
	542053, 80	541019	541012	541007
Ford 8.8, 31 Tooth	542025	541020	541013	541008
	542054	541021	541013	541008
Ford 8" & 9"	542036, 43, 59	541023	541015	541010
Ford 9.75	542090	541043	541044	541042
Ford 10 1/4	542089	541045	541046	541047
Chrysler 9 1/4	542070, 71	541038	541039	541040
Chrysler 8 1/4	542072, 74	541041	541012	541007

Chrysler 8 3/4	542051	541022	541014	541024
AMC Model 20	542081	541019	541012	541007
Toyota Landcruiser	542030	541022	541014	541009
Dana Model 44	542081, 82, 83, 84	541019	541012	541007
				541048
Buick/Olds/Pontiac 8.2	542099	541035	541036	

Service Kit Availability

Part Number	Unit in Stock	Part Number	Unit in Stock	Part Number	Unit in Stock
Spring Retainer Service Kits					
541016	Yes	541021	Yes	541038	Yes
541017	Yes	541022	Yes	541041	Yes
541018	Yes	541023	Yes	541043	No
541019	Yes	541035	Yes	541045	Yes
541020	No				
Pinion Gear Service Kits					
541011	No	541014	Yes	541039	No
541012	No	541015	No	541044	Yes
541013	No	541036	Yes	541046	No
Pinion Shaft Service Kits					
541005	No	541009	Yes	541040	No
541006	Yes	541010	No	541042	Yes
541007	No	541024	Yes	541047	Yes
541008	Yes	541037	No	541048	Yes



Made in the United States of America